



PRE-OWNED EQUIPMENT

CONDITION REPORT

Used Scissor Lift

Manufacturer: JLG	Model: Toucan Junior 6	Year: 2007	Hours: 9 (as on clock)
Serial number: A130016594	Plat. Size: 3'	Fuel type: Electric	Drive: 2WD

Additional options (check all that apply): Airline Worklights Generator
Cold Weather Pkg Motion Alarm Beacon Welder/Weld Leads Inverter

JLG Branded Options (Check all that apply) Skypower Skywelder SkyGlazier
Soft Touch System Other (please specify)

			Poor	Fair	Average	Good	Excellent
OVERALL APPEARANCE							
Paint – coverage/rust			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Paint – customer colors	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Exterior body panels			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
FRAME AREA – STRUCTURAL ISSUES? EXPLAIN	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>					
LEAKS – MACHINE FREE FROM LEAKS? EXPLAIN	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
WHEELS/TIRES Air <input type="checkbox"/> Foam Filled <input type="checkbox"/> Non-mark <input checked="" type="checkbox"/> Air Boss <input type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
All four tires match?	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Sidewalls free of cuts?	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Tread: L.F. 80% R.F. 80% L.R. 80% R.R. 80%							
ENGINE AREA			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Starter engages properly	Yes <input type="checkbox"/>	No <input type="checkbox"/>					
Engine smokes?	Yes <input type="checkbox"/>	No <input type="checkbox"/>					
Engine misses?	Yes <input type="checkbox"/>	No <input type="checkbox"/>					
Record engine serial number							
SCISSOR ARMS			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Scissor arms aligned and free of defects	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Hoses and cables free of cuts/damage	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
PLATFORM			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Platform rails intact, free of damage	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Platform extension extends/retracts freely	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Platform door latches properly	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
UPPER CONTROL BOX			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Decals legible – installed properly	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Controllers free from damage	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
LOWER CONTROL BOX			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Decals legible – installed properly	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Toggle switches free from damage	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					

Excellent – Like new, recently replaced
Good – Functions as it should, with little wear
Average – Operates as expected for this type/year of equipment

Putting your work above everything.™

CONDITION REPORT



PRE-OWNED EQUIPMENT

FUNCTIONAL TESTING

	Pass	Fail	N/A
UPPER CONTROLS			
Drive Forward	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Drive Reverse	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Steer Left	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Steer Right	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Crab Steer	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Compound Steer	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Lift Up/Down	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Test High Engine RPM and High Wheel Speeds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Auxiliary Power	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
LOWER CONTROLS			
Lift Up/Down	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Auxiliary Power	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Manual Descent	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments: New batteries installed on the machines - 07/08/2019 (by ML)
Slight paint loss on platform no rust
Machine in good condition for age
CHARGER WORKS CORRECTLY - MACHINE OPERATES CORRECTLY (by ML
07/08/2019)

Putting your work above everything.™

Inspected by: J. Barker

Date: 01/08/2019