



PRE-OWNED EQUIPMENT

# CONDITION REPORT

Used Boom Lift

Manufacturer: JLG	Model: 460 SJ	Year: 2007	Hours: 2548
Serial number: 0300121771	Plat. Size:	Fuel type: Diesel	Drive: 4WD

Additional options (check all that apply): Airline  Worklights  Generator   
Cold Weather Pkg  Motion Alarm  Beacon  Welder/Weld Leads  Inverter

JLG Branded Options (Check all that apply) Skypower  Skywelder  SkyGlazier  
Soft Touch System  Other  (please specify)

			Poor	Fair	Average	Good	Excellent
<b>OVERALL APPEARANCE</b>							
Paint – coverage/rust			<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Paint – customer colors	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Exterior body panels			<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<b>FRAME AREA – STRUCTURAL ISSUES? EXPLAIN</b>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>					
<b>LEAKS – MACHINE FREE FROM LEAKS? EXPLAIN</b>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>					
<b>WHEELS/TIRES</b> Air <input type="checkbox"/> Foam Filled <input checked="" type="checkbox"/> Non-Mark <input type="checkbox"/> Air Boss <input type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
All four tires match?	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Sidewalls free of cuts?	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>					
Tread: L.F. 70% R.F. 70% L.R. 70% R.R. 70%							
<b>ENGINE AREA</b>							
Starter engages properly	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>					
Engine smokes?	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>					
Engine misses?	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>					
Record engine serial number							
<b>BOOM</b>							
Boom sections aligned and free of defects	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>					
Powertrack aligned properly	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>					
Hoses and cables free of cuts/damage	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>					
<b>PLATFORM</b>							
Platform rails intact, free of damage	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Platform door latches properly	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
<b>UPPER CONTROL BOX</b>							
Decals legible – installed properly	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Controllers free from damage	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>					
<b>LOWER CONTROL BOX</b>							
Decals legible – installed properly	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					
Toggle switches free from damage	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>					

Excellent – Like new, recently replaced  
Good – Functions as it should, with little wear  
Average – Operates as expected for this type/year of equipment  
Fair – Operates but shows signs of needing repair  
Poor – Does not operate or needs immediate attention

Putting your work above everything.™



PRE-OWNED EQUIPMENT

# CONDITION REPORT

Used Boom Lift

## FUNCTIONAL TESTING

	Pass	Fail	N/A
<b>UPPER CONTROLS</b>			
Drive Forward	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Drive Reverse	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Steer Left	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Steer Right	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Crab Steer	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Compound Steer	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Main Boom Lift Up/Down	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Main Boom Telescope In/Out	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Lower Boom Lift Up/Down	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lower Boom Telescope In/Out	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Platform Level Up/Down	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Platform Rotate Left/Right	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Jib Up/Down	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Jib Swing Left/Right	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Turntable Swing Left/Right	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Test High Engine RPM and High Wheel Speeds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Auxiliary Power	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<b>LOWER CONTROLS</b>			
Main Boom Lift Up/Down	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Main Boom Telescope In/Out	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Lower Boom Lift Up/Down	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lower Boom Telescope In/Out	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Platform Level Up/Down	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Platform Rotate Left/Right	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Jib Up/Down	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Jib Swing Left/Right	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Turntable Swing Left/Right	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Auxiliary Power	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Manual Descent	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments: - Rear right tire damaged - Various hoses porous and up to the wire braid scrubbed  
 - Leakage at the rotating union  
 - lifting cylinder slight leakage -

Putting your work above everything.™

Inspected by: U.Wiards

Date: 30.06.2021